



MONITOUCH TECHNOSHOT

Waterproof Gasket OPERATING INSTRUCTIONS

Thank you for purchasing the waterproof gasket, "TS1070S-WP/TS1100S-WP".


This is a waterproof gasket to keep the protection structure for the front of TS1000 Smart series compliant with IP65. Make sure that the delivered unit conforms to your requirement.

This manual describes the product configuration and the mounting procedure.

Before using the product, read this manual carefully and make sure you understand them.

Items


OPERATING INSTRUCTIONS (This manual) : 1 copy, Gasket : 1 pce




Mounting Procedure

1. Attach the waterproof gasket to the rear side of TS1000 Smart series.
2. Embed the gasket side by side to fit into the groove.

Example : TS1070Si



3. Install the TS1000 Smart series unit to the mounting panel and tighten the four fixtures supplied with TS1000 Smart series.



FE HAKKO Electronics Co., Ltd.

890-1, Kamikashiwano-machi, Hakusan-shi, Ishikawa, 924-0035 Japan

TEL : 81-76-274-2144 <http://www.monitouch.com>

Importer in Europe

Fuji Electric Europe GmbH Goethering 58, 63067 Offenbach / Main, Germany




MONITOUCH TECHNOSHOT 防水パッキン取扱説明書

このたびは、防水パッキン「TS1070S-WP/TS1100S-WP」をお買い上げいただき、誠にありがとうございます。本製品は、TS1000 Smartシリーズ前面の保護構造をIP65相当に保つために使用します。はじめに、ご希望通りの商品であるかをご確認ください。本書は防水パッキンの付属品、取付手順を述べたものです。十分に内容をご理解の上ご使用ください。

付属品


取扱説明書(本書) : 1部、防水パッキン : 1個




取付手順

1. TS1000 Smartシリーズの背面に防水パッキンをはめ込みます。
2. 溝に納まるように、防水パッキンの上からまんべんなく押します。

例 : TS1070Si



3. 板金パネルに取り付け、TS1000 Smartシリーズ付属の取付金具4個で固定します。



产品中有害物质的名称及含量



部名称	有害物質					
	鉛 (Pb)	汞 (Hg)	镉 (Cd)	六价铬 (Cr (VI))	多溴联苯 (PBB)	多溴二苯醚 (PBDE)
本身	○	○	○	○	○	○

本表格依据SJ/T 11364的规定编制。
○表示该有害物质在该部件所有均质材料中的含量均在GB/T 26572规定的限量要求以下。
×表示该有害物质至少在该部件的某一均质材料中的含量超出GB/T 26572规定的限量要求。

产品合格证

产品名称 : 程序操作显示器
本产品经检验合格准予出厂。
Hakko Electronics Co., Ltd.
邮政编码: 924-0035
日本国石川县白山市上柏野町890番1

発紘電機株式会社

〒924-0035 石川県白山市上柏野町890番1 URL <http://www.hakko-elec.co.jp>
モニタッチコールセンター フリーコール 0120-128-220